



MULTI INTERNATIONAL GOLD MEDALS & AWARD WINNING PRODUCTS



ATOM AIRLIFT® 2 & 4-STROKE BLOWER ATTACHMENTS FITTING INSTRUCTIONS


Vacuum Attachment - Page 1&2


Sprayer Attachment - Page 3


Roof Gutter Cleaning – Page 4
Attachment


Hand Blower Vacuum Attachment: Assembly & Operation


A. TO FIT BLOWERS WITH TUBE LOCK SCREW (AS SHOWN IN FIG.5A)


















Hand Blower Vacuum Attachment: Assembly & Operation


B. TO FIT BLOWERS WITH 4 SCREW POSTS UNDER INTAKE COVER (AS SHOWN IN FIG.3B)
































! NOTE

Avoid using vacuum in areas where stones or other large hard debris may be vacuumed into the unit. Clear these areas first, so only light debris is left to be vacuumed.

A WARNING - DANGER

DO NOT let bag get close to exhaust outlet as bag or contents could ignite.




DO NOT vacuum wet leaves (it may be dry on top) but underneath it could be wet.

! NOTE


Be aware that the unit is not designed to vacuum abrasive objects such as sand, crushed rock, stones or pebbles, muddy material, all of which will cause rapid wear of vacuum tubes and fan blades with major decrease in the vacuum or fan blowing capacity. Wear caused by long term use (especially professionally) is a normal wear and tear situation and when considererably worn parts should be replaced by operator or your servicing dealer.


Hand Blower Spray Attachment: Assembly & Operation




























WARNING Wear protective clothing, goggles and mask. Spraying some types of chemicals can be hazardous to the operator and surrounding area. Use spray solutions only as directed by the manufacturer. Read the manufacturer's or supplier's instructions very carefully. If in doubt do not use before seeking further advice. Do not spray in windy conditions. Do not overspray, or allow wind drift to take spray liquids to neighbouring properties. Be care when using sprays of any type.

STORAGE & DISPOSAL

Keep out of reach of children. Store chemicals in the closed original container, in a dry cool place with the blower attachment, pressure bottle and spray nozzle assembly.

Dispose of empty containers, by wrapping in paper, placing in a sealed plastic bag and disposing of according to regulations.


FIRST AID


If poisoning occurs contact a Doctor or Poisons Information Centre. Phone 131 126.


LIABILITY


Any chemical used for spraying must be used strictly as directed by the supplier or manufacturer. Atom Industries is not liable for loss or damage arising from failure to follow directions of use.


Hand Blower Gutter Attachment: Assembly & Operation














! NOTE


Due to working angle of fuel tank when gutter cleaning, ensure that fuel tank is full.

DO NOT ACCELERATE engine until sliding elbow is **RESTING** on gutter edge.

With sliding elbow resting on gutter edge, accelerate engine and **SLIDE** elbow along gutter quickly and easily.

A WARNING

DO NOT use in wet conditions and/or close to power lines.



///ATOM[®]

Premium Technology & Unrivalled Endurance

Atom Industries is a division of Solo Industries Pty Ltd – an Australian owned company that invents, designs and manufactures unique and outstanding products for local tough and hard Australian conditions with a history of international award winning gold medals, great backup and service since 1961.

Atom products are extensively protected by many Patents, Registered Designs, Patents Pending and Shape Trade Marks.

Atom has a policy of continuous product improvement and development and reserves the right to change design and appearance of products without notice.

PAGE 4 170816 21777